

## Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID: 4996  
 FACILITY: American Energy Corp Century Mine  
 LOCATION: 43521 Mayhugh Hill Rd Twp Hwy 88  
 Beallsville, OH 43716  
 COUNTY: Belmont  
 DISTRICT: SEDO

STATUS: Original  
 PERMIT NUMBER: 01L00091\*GD  
 STATION CODE: 014  
 MONITORING PERIOD : 2008-02-01 To: 2008-02-29  
 REPORTING LAB: Tar-Det Inc.  
 ANALYST: Laura K Wright  
 NO DISCHARGE INDICATOR: AL

PARAMETER	Residue, Total Dissolved						
PARAMETER CODE	00515						
UNITS	4106						
FREQUENCY	1 / 2 Weeks						
SAMPLING TYPE	Grab						
2008-02-01							
2008-02-02							
2008-02-03							
2008-02-04							
2008-02-05							
2008-02-06							
2008-02-07							
2008-02-08							
2008-02-09							
2008-02-10							
2008-02-11							
2008-02-12							
2008-02-13							
2008-02-14							
2008-02-15							
2008-02-16							
2008-02-17							
2008-02-18							
2008-02-19							
2008-02-20							
2008-02-21							
2008-02-22							
2008-02-23							
2008-02-24							
2008-02-25							
2008-02-26							
2008-02-27							
2008-02-28							
2008-02-29							
Minimum							
Maximum							
Average							
Count							
Name of Responsible Official or Authorized Representative	I certify under the penalty of law that I have personally examined and am familiar with the information submitted herein and based on my inquiry of those individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.				Signature of Responsible Official or Authorized Representative		Submission Date/Time
Adam Hartley							2008-03-19

Page 10